

|              |          |                |             |          |  |
|--------------|----------|----------------|-------------|----------|--|
| Applications | Features | Specifications | Accessories | Download |  |
|--------------|----------|----------------|-------------|----------|--|

| Features                          | 3385  | 3386  |
|-----------------------------------|-------|-------|
| Current measurement               | AC    | AC/DC |
| LCD display counts with backlight | 50000 | 50000 |
| 3000A ACA Flexible clamp          | *     | *     |
| AC True RMS                       | *     | *     |
| Flashlight                        | *     | *     |
| Data Hold & Peak Hold             | *     | *     |
| Max /Min                          | *     | *     |
| REL (Zero) Function               | *     | *     |
| Auto Power Off                    | *     | *     |
| Low battery indication            | *     | *     |
| 1.9" (48mm) Jaw opening           | *     | *     |
| NCV Detection & flashlight        | *     | *     |
| Inrush Current                    | *     | *     |

**Size(HxWxD):** 230mm x 76mm x 40mm

**Weight:** 315g

|              |          |                |             |          |  |
|--------------|----------|----------------|-------------|----------|--|
| Applications | Features | Specifications | Accessories | Download |  |
|--------------|----------|----------------|-------------|----------|--|

| Specifications     |                              |  |      |      |
|--------------------|------------------------------|--|------|------|
| Function           | Max. Range                   | Basic Accuracy                                       | 3385 | 3386 |
| Voltage DC         | 1000V                        | $\pm(0.1\%+4d)$                                      | *    | *    |
| Voltage AC         | 1000V                        | $\pm(1.0\%+3d)$                                      | *    | *    |
| Current DC         | 1000A                        | $\pm(2.5\%+5d)$                                      |      | *    |
| Current AC         | 1000A                        | $\pm(2.5\%+5d)$                                      | *    | *    |
| Resistance         | 50M $\Omega$                 | $\pm(3.0\%+5d)$                                      | *    | *    |
| Temperature        | 1000°C/ 1832°F               | $\pm(1.0\%+2.5^{\circ}\text{C}/4.5^{\circ}\text{F})$ | *    | *    |
| Capacitance        | 5mF                          | $\pm(3.5\%+10d)$                                     | *    | *    |
| Frequency          | 10MHz                        | $\pm(0.3\%+2d)$                                      | *    | *    |
| ACA flexible clamp | 3000A                        | $\pm(2.8\%+8d)$                                      | *    | *    |
| Continuity check   | Buzzer sounds at 50 $\Omega$ |  |      |      |
| Diode test         | Test current 0.3mA           |  |      |      |